


## FRESA DE TOPO PARA CHANFRAR

60° - 90°



| Código                          | d1 | a°  | l2 | l1  | z |
|---------------------------------|----|-----|----|-----|---|
| F MD D 4MM 3C 60° CHANFRAR S/C  | 4  | 60° | 2  | 60  | 3 |
| F MD D 6MM 4C 60° CHANFRAR S/C  | 6  | 60° | 3  | 60  | 4 |
| F MD D 8MM 4C 60° CHANFRAR S/C  | 8  | 60° | 4  | 80  | 4 |
| F MD D 10MM 6C 60° CHANFRAR S/C | 10 | 60° | 5  | 100 | 6 |
| F MD D 12MM 6C 60° CHANFRAR S/C | 12 | 60° | 6  | 120 | 6 |

| Código                          | d1 | a°  | l2 | l1  | z |
|---------------------------------|----|-----|----|-----|---|
| F MD D 4MM 3C 90° CHANFRAR S/C  | 4  | 90° | 2  | 60  | 3 |
| F MD D 6MM 4C 90° CHANFRAR S/C  | 6  | 90° | 3  | 60  | 4 |
| F MD D 8MM 4C 90° CHANFRAR S/C  | 8  | 90° | 4  | 80  | 4 |
| F MD D 10MM 6C 90° CHANFRAR S/C | 10 | 90° | 5  | 100 | 6 |
| F MD D 12MM 6C 90° CHANFRAR S/C | 12 | 90° | 6  | 120 | 6 |